

# Return LCD Packing Guide

Need to return an LCD? No problem! Use our easy guides to safely package parts to ensure no damage occurs during shipping. Failure to do so could result in parts an ineligible return.

**To get started, you'll need a sturdy box, the return LCD in its original packaging or bubble pouch, bubble wrap, and packing tape.**



Step 1: Line bottom of the box with protective bubble.



Step 2: Place LCD in original packaging or bubble pouch on top of bubble.



Step 3: Place bubble over LCD. Use enough bubble to prevent movement. If returning multiple LCDs, secure each part in its original packaging or protective bubble.



Step 4: Tape box and affix mailing label to ship back to AGP.



**Questions?** Contact your dedicated sales executive or email [sales@agpartseducation.com](mailto:sales@agpartseducation.com).